


How to install the Touchwin USB driver


This driver is fit for win7-32 bit, win XP, win 98 system.

1. Do not connect Touchwin HMI to your PC. Close all the antivirus software in your PC.
2. Open the installation file, right click "XNETDrvInst.exe", and choose "Run as administrator".

Then finish the installation according to the installation guide.



3. After installing the driver successfully, you can find the Xinje TH USB device in device manager.



4. Now you can connect Touchwin HMI to PC and power on it to download program.

Notes:

If the HMI still cannot download program, please try the following methods:

1. Disconnect and connect the cable again.
2. Repower on the Touchwin HMI.
3. Use force download. (turn on DIP switch 2 behind the Touchwin HMI, repower on).